

# Non-Skid Industrial Rug

---

### I. Manufacturer Identification

Manufacturers Name: Breg Environmental  
Address: 20 Joseph Mills Drive, PO Box 595 Fredericksburg, VA 22404-0595  
Phone Number: 540-373-3482 or 800-433-1013  
Date Prepared: March 26, 2010

### II. Ingredients/Identity Information

Hazardous Components: (Specific Chemical Identity Common Names)

No Hazardous Components

Polypropylene Fiber CAS# 25085-53-4  
Ethylene Vinyl Acetate Film CAS# N/A

Other Limits:

OSHA(PEL): N/A

ACGLIH(TLV): N/A

Other Limits Recommended: N/A

### III. Physical/Chemical Characteristics

Boiling Point: N/A

Vapor Pressure (mmHg): N/A

Vapor Density (AIR=1): N/A

Solubility in water: Insoluble

Appearance and Odor: Grey Fibrous Material with an Ethylene Vinyl Acetate Backing

Specific Gravity (H<sub>2</sub>O=1):

Melting Point:

Evaporation Rate (Butyle Acetate=1):

### IV. Fire and Explosion Hazard Data

Flash Point: >600° F

Flammable Limits: **LEL:** N/A **UEL:** N/A

Extinguishing Media: Water fog, water spray, foam or dry chemical

Special Fire Fighting Procedures: Use full bunker gear including NIOSH approved self-contained breathing apparatus.

Unusual Fire and Explosion Hazards: Treat as a solid that burns generally with low smoke density.

## V. Reactivity Data

Stability: Unstable  Stable

Conditions to Avoid:

Incompatibility (Materials to Avoid): Strong oxidizing agents.

Hazardous Decomposition or By-products: carbon dioxide, carbon monoxide, and small amounts of Aliphatic and aromatic hydrocarbons.

Hazardous Polymerization: Will not occur.

## VI. Health Hazard Data

Route of Entry: Inhalation? Dust

Skin? N/A

Ingestions? N/A

Health Hazards (Acute and Chronic):

Carcinogenicity: N/A

Signs and Symptoms of Exposure: Product fumes and dust may cause irritation.

Medical Conditions Generally Aggravated by Exposure: Pre-existing eye and respiratory disorders may be aggravated.

Emergency and First Aid Procedures: Flush eyes with water. For molten contact, treat as burn.

## VII. Precautions for Safe Handling and Use

Steps to Be Taken in Case Material is Released or Spilled: Shovel, sweep or vacuum. Avoid generating dust clouds.

Waste Disposal Method: Check with your Local, State and Federal regulatory agencies.

Steps to Be Taken in Handling and Storing: Treat as a solid that can burn. Store away from oxidizing materials.

Other Precautions: N/A (Refer to absorbed fluid(s) MSDS, because this product does not render fluids non-flammable, neutral or less hazardous.)

## VIII. Control Measures

Respiratory Protection: Respirator approved for nuisance dust.

Ventilation: Local Exhaust? N/A

Mechanical(general): Recommended

Special: N/A

Other: N/A

Protective Gloves: Not required

Eye Protection: Safety Glasses

Other Protective Clothing or Equipment: N/A

Work/Hygienic Practices: Good industrial hygienic procedures.



PO Box 595 Fredericksburg, Virginia 22404  
1-800-433-1013 | [www.bregenvironmental.com](http://www.bregenvironmental.com)

## Material Safety Data Sheet

**The above information is based on the data of which we are aware and is believed to be correct as of the date hereof. Since this information may be applied under conditions beyond our control and with which we may be unfamiliar and since data made available subsequent to the date hereof may suggest modifications of the information, we do not assume any responsibility for the results of its use. This information is furnished upon condition that the person receiving it shall make his own determination of the suitability of the material for his particular purpose.**